SYSTEM NO.	**SSXAU382**
DESCRIPTION	Turbo-back including Hi-Flow Sports Cat
NOTES	Requires Stage 2 ECU remap

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSAU617	**Front Connecting Pipe**	**1**	
CHC79SS	79mm Band Clamp - 304 S/S	1	
MSAU618	**Centre Silencer**	**1**	
CHC68SS	68mm Band Clamp - 304 S/S	1	
CHC79SS	79mm Band Clamp - 304 S/S	1	
F20050	5.0mm Spacer	2	
F5125	Adaptor Sleeve 76.2mm 1.5 304 X 170 (65 Id)	1	
MSAU619	**Rear Silencer Assembly {valve motor from the OE exhaust is required for fitment}**	**1**	
CHC79SS	79mm Band Clamp - 304 S/S	1	
F3160	Wire Formed Spring Assembly	2	
M5FLGNUT	M5 X 0.8 Nylon Coat Flange Nut	6	
MSVAG05	**Cast Large Bore Downpipe 200cell HJS Catalyst {Replaces MSAU616}**	**1**	
18MMWASHER	18mm Copper Washer	2	
8MMWASHER	8mm Flat Washer Bzp	2	
F7042		1	
M18BLANKSC	M/S/Zinc M18 Blanking Plug	2	
M8X16BZP	M8X16mm Bzp Set Screw-Zinc Pl.	2	
MSVW372	**Cerakote Black Tips**	**4**	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	4	

TECHNICAL INFORMATION

Master Copy Approved By: MILLTEK

NOTES	OE rear silencer hanger brackets need to be rotated 180° as per below images:

OE Position:



Rotated 180°:

