SYSTEM NO.	SSXAU448
DESCRIPTION	Cat-back
NOTES	2016 and later models have an updated valve location on one rear silencer meaning the wiring loom needs extending to accommodate.

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSAU568	**LH Front Pipe Assembly**	**1**	
MSAU569	**RH Front Pipe Assembly**	**1**	
MSAU570REP	**Centre Silencer Replacement Assembly**	**1**	
8MMWASHER	8mm Flat Washer Bzp	1	
CHC73SS	73mm Band Clamp 304 S/Steel	2	
M8BZPFLNUT	M8 Bzp Flange Nut Serrated Only	1	
M8X16BZP	M8X16mm Bzp Set Screw-Zinc Pl.	1	
MSAU627	**LH ValveSonic Rear Silencer**	**1**	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
F3160	Wire Formed Spring Assembly	1	
M5FLGNUT	M5 X 0.8 Nylon Coat Flange Nut	3	
MSAU628	**RH ValveSonic Rear Silencer**	**1**	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
F3160	Wire Formed Spring Assembly	1	
M5FLGNUT	M5 X 0.8 Nylon Coat Flange Nut	3	
MSVW372	**Cerakote Black Tips**	**4**	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	4	

TECHNICAL INFORMATION

NOTES	2016 and later models have an updated valve location on one rear silencer meaning the wiring loom needs extending to accommodate.