| | |
|---|---|
| **SYSTEM NO.** | **SSXAU560** |
| **DESCRIPTION** | Cat-back |
| **NOTES** | Recommend with Valve Delete Modules SSXAU405 to prevent ECU fault codes |

## PARTS REQUIRED

| PART NO. | DESCRIPTION | QUANTITY | IN PACKAGE |
|---|---|---|---|
| **MSAU568** | **LH Front Pipe Assembly** | **1** | |
| **MSAU569** | **RH Front Pipe Assembly** | **1** | |
| **MSAU570** | **Centre Silencer Assembly** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 2 | |
| **MSAU571** | **LH Rear Silencer Assembly** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| **MSAU572** | **RH Rear Silencer Assembly** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| **MSVW372** | **Cerakote Black Tips** | **4** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 4 | |

## TECHNICAL INFORMATION

| | |
|---|---|
| **NOTES** | Recommend with Valve Delete Modules SSXAU405 to prevent ECU fault codes |