SYSTEM NO.	SSXAU737
DESCRIPTION	Cat-back
NOTES	Recommended with Valve Delete Modules SSXAU405 to prevent ECU fault codes

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSAU568	**LH Front Pipe Assembly**	**1**	
MSAU569	**RH Front Pipe Assembly**	**1**	
MSAU570REP	**Centre Silencer Replacement Assembly**	**1**	
8MMWASHER	8mm Flat Washer Bzp	1	
CHC73SS	73mm Band Clamp 304 S/Steel	2	
M8BZPFLNUT	M8 Bzp Flange Nut Serrated Only	1	
M8X16BZP	M8X16mm Bzp Set Screw-Zinc Pl.	1	
MSAU571	**LH Rear Silencer Assembly**	**1**	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
MSAU572	**RH Rear Silencer Assembly**	**1**	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
MSVW372	**Cerakote Black Tips**	**4**	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	4	

TECHNICAL INFORMATION

NOTES	Recommended with Valve Delete Modules SSXAU405 to prevent ECU fault codes