| | |
|---|---|
| **SYSTEM NO.** | SSXBM1223 |
| **DESCRIPTION** | Cat-back |
| **NOTES** | OPF/GPF Bypass Requires Stage 2 ECU Software |

## PARTS REQUIRED

| PART NO. | DESCRIPTION | QUANTITY | IN PACKAGE |
|---|---|---|---|
| **MSAU601** | **LH Polished Tip Assembly** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| **MSAU602** | **RH Polished Tip Assembly** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| **MSBM338** | **Rear Silencer Assembly** | **1** | |
| CHC79SS | 79mm Band Clamp - 304 S/S | 2 | |
| **MSBM341** | **LH Outlet Pipe to Milltek Trims** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| **MSBM342** | **RH Valved Outlet Pipe to Milltek Trims** | **1** | |
| 6MMSPRING | 6mm S/Steel Spring Washer | 3 | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| M6NYLOC | M6 Nyloc Nutbzp | 3 | |
| M6X16BUTT | M6 X 16mm Socket Button Head | 3 | |
| **MSBM343** | **Front Connecting Pipe** | **1** | |
| **MSBM344** | **Y Pipe Section** | **1** | |
| CHC83SS | 83mm Band Clamp - 304 S/S | 1 | |
| **MSBM398** | **LH Connecting Pipe** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| **MSBM399** | **RH Connecting Pipe** | **1** | |
| CHC79SS | 79mm Band Clamp - 304 S/S | 1 | |
| **MSBM400** | **LH Connecting Pipe** | **1** | |
| CHC79SS | 79mm Band Clamp - 304 S/S | 1 | |
| **MSBM401** | **RH Connecting Pipe** | **1** | |
| CHC79SS | 79mm Band Clamp - 304 S/S | 1 | |

## TECHNICAL INFORMATION

| | |
|---|---|
| **NOTES** | OPF/GPF Bypass Requires Stage 2 ECU Software |

Master Copy Approved By: MILLTEK

MILLTEK

Master Copy Approved By: MILLTEK