SYSTEM NO.	**SSXRR113/114/115/116/117**


VEHICLES	YEARS
RANGE SPORT SVR 5.0 V8 SUPERCHARGED	2018 to 2022

NOTES	Insert

TECHNICAL INFORMATION

NOTES	Original silencers can be refitted again using the new Milltek brackets if required.

1. Rear silencers need cutting at the dimples below the bracket on both sides.





2. OE Hanger bracket needs cutting off on both sides as shown, the new Milltek hanger must be used to make room for the tips, OE rear silencers can be reinstalled using the new hanger if needed.





