SYSTEM NO.	**SSXFD017**
DESCRIPTION	Cat Replacement Pipe
NOTES	Will cause CEL (check engine light) to come on. Milltek Cat-back Only

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSFD82	**De-Cat Pipe (Standard Ford or Milltek Manifold)**	**1**	
10MMWASHER	10mm Flat Washer Bzp	2	
M10FLGNUT	M10 Bzp Flange Nutserrated Only	2	
M10X35BZP	M10 X 35mm Bzp Set Screw	2	

TECHNICAL INFORMATION

NOTES	Will cause CEL (check engine light) to come on. Milltek Cat-back Only