SYSTEM NO.	**SSXSE144**
DESCRIPTION	Turbo-back excluding Hi-Flow Sports Cat
NOTES	Requires Stage 2 ECU remap

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSSE132REP	**Large-bore Downpipe and Decat**	**1**	
6MMWASHER	M6X25 S/Steel Repair Washer	2	
M6X10SET	M6X10 Bzp Hex Set Bolts Screw	2	
MSSE133	**Flex Connecting Pipe**	**1**	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
MSSE134	**Centre Silencer Replacement Pipe**	**1**	
CHC58SS	58mm Band Clamp - 304 S/Steel	1	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
F5079	Adaptor Sleeve 70mm 1.5 304 X 120mm (55.5 Id)	1	
MSSE135	**Rear Silencer Assembly**	**1**	
8MMWASHER	8mm Flat Washer Bzp	1	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
F7060	Loose Xenon Sensor Bracket	1	
M8X16BZP	M8X16mm Bzp Set Screw-Zinc Pl.	1	
MSSE136	**Tip Assembly**	**1**	
CHC73SS	73mm Band Clamp 304 S/Steel	1	

TECHNICAL INFORMATION

F7060 Xenon sensor bracket location:

MILLTEK

