
| SYSTEM NO. | SSXTY209 |
|---|---|
| DESCRIPTION | Particulate Filter-back |
| NOTES | |

## PARTS REQUIRED

| PART NO. | DESCRIPTION | QUANTITY | IN PACKAGE |
|---|---|---|---|
| **MSTIP244** | **Jet-115 Carbon Trims** | **2** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 2 | |
| **MSTY145REP** | **Centre Silencer Bypass** | **1** | |
| M10FINENUT | M10 X 1.25 Bzp Flange Nut Serrated Only | 2 | |
| **MSTY146** | **Rear Silencer** | **1** | |
| 8MMWASHER | 8mm Flat Washer Bzp | 2 | |
| CHC79SS | 79mm Band Clamp - 304 S/S | 1 | |
| EBC4499 | Mounting Rubber | 1 | |
| F7066 | Loose Mounting Cradle | 1 | |
| F7094 | Loose Mounting Bracket | 1 | |
| M8BZPFLNUT | M8 Bzp Flange Nut Serrated Only | 4 | |
| M8X16BZP | M8X16mm Bzp Set Screw-Zinc Pl. | 2 | |
| **MSTY147** | **Outlet Pipes (2 Per Car)** | **2** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 2 | |

## TECHNICAL INFORMATION

| | |
|---|---|
| NOTES | Rear Silencer additional mounting bracket, cradle and bush bolt through existing holes behind the OE LH exhaust hanger mount as per below images.<br><br>We recommend loosely installing the exhaust clamps then aligning the system to ensure there is adequate clearance between the centre silencer and the propshaft. |



MILLTEK



Master Copy Approved By: MILLTEK