| | |
|---|---|
| **SYSTEM NO.** | **SSXTY130** |
| **DESCRIPTION** | Particulate Filter-back |
| **NOTES** | |


## PARTS REQUIRED

| PART NO. | DESCRIPTION | QUANTITY | IN PACKAGE |
|---|---|---|---|
| **MSTIP253** | **4.5" Burnt Titanium Tips** | **2** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 2 | |
| **MSTY112REP** | **Centre Silencer Delete Pipe** | **1** | |
| 10MMWASHER | 10mm Flat Washer Bzp | 2 | |
| F3031 | Gasket 1.5mm | 1 | |
| M10FLGNUT | M10 Bzp Flange Nutserrated Only | 2 | |
| M10X35BZP | M10 X 35mm Bzp Set Screw | 2 | |
| **MSTY113** | **Rear Silencer Assembly** | **1** | |
| 8MMWASHER | 8mm Flat Washer Bzp | 2 | |
| CHC79SS | 79mm Band Clamp - 304 S/S | 1 | |
| EBC4499 | Mounting Rubber | 1 | |
| F7066 | Loose Mounting Cradle | 1 | |
| F7094 | Loose Mounting Bracket | 1 | |
| M8BZPFLNUT | M8 Bzp Flange Nut Serrated Only | 4 | |
| M8X16BZP | M8X16mm Bzp Set Screw-Zinc Pl. | 2 | |
| **MSTY114** | **Outlet Pipes** | **2** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 2 | |

MILLTEK

## TECHNICAL INFORMATION

| | |
|---|---|
| NOTES | Rear Silencer additional mounting bracket, cradle and bush bolt through existing holes behind the OE LH exhaust hanger mount as per below images.<br><br>We recommend loosely installing the exhaust clamps then aligning the system to ensure there is adequate clearance between the centre silencer and the propshaft. |



MILLTEK



Master Copy Approved By: MILLTEK