| | |
|---|---|
| SYSTEM NO. | SSXFD367 |
| DESCRIPTION | Cat-back |
| NOTES | |


## PARTS REQUIRED

| PART NO. | DESCRIPTION | QUANTITY | IN PACKAGE |
|---|---|---|---|
| **ACTUATOR01** | **Valve Motor (Required on Post Sept 2020 Cars Only) MOO-33** | **1** | |
| **F5084** | **Adapter for OE Downpipe** | **1** | |
| CHC63SS | 63mm Band Clamp 304 S/Steel | 1 | |
| **MSFD244** | **Axle Pipe** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| **MSFD245** | **Rear Silencer** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| **MSFD246** | **Valve Assembly Pipe** | **1** | |
| 6MMSPRING | 6mm S/Steel Spring Washer | 3 | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 1 | |
| F7091 | Valve Motor Drive Shaft -Offset | 1 | |
| M6X16BUTT | M6 X 16mm Socket Button Head | 3 | |
| **MSFD273** | **Valve Extension Pipe** | **1** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 1 | |
| **MSFD274** | **Connecting Pipe** | **1** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 1 | |
| **MSFD275** | **Tail Pipe** | **1** | |
| 8MMWASHER | 8mm Flat Washer Bzp | 3 | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 1 | |
| EBC4499 | Mounting Rubber | 1 | |
| F7066 | Loose Mounting Cradle | 1 | |
| F7093 | Mounting Bracket | 1 | |
| M8BZPFLNUT | M8 Bzp Flange Nut Serrated Only | 6 | |
| M8X16BZP | M8X16mm Bzp Set Screw-Zinc Pl. | 2 | |
| M8X35BZP | M8 X 35mm Bzp Hex Setzinc | 1 | |
| **MSTIP199** | **4.0" Polished Tips** | **2** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 2 | |

MILLTEK

## TECHNICAL INFORMATION

## OE CUTTING INSTRUCTIONS




## MSFD245 CUTTING INSUTRUCTIONS





CUT 165MM OFF THE LONG OUTLET FROM THE MSFD245 AND REMOVE ANY BURRS AND SHARP EDGES FROM CUTTING

Master Copy Approved By: MILLTEK

MILLTEK

# BUMPER SUPPORT BAR & MOUNTING BRACKET





USE THE M8 X 35MM LONG BOLT TO ATTACH THE BUMPER SUPPORT, THIS PROVIDES 3 LEVEL SUPPOORTS FOR THE MOUNTING BRACKET

ATTACHED THE BRACKET SUPPLIED ONTO THE BOLTS ANSD SECURE USING FLANGE NUTS

Master Copy Approved By: MILLTEK