| | |
|---|---|
| **SYSTEM NO.** | SSXVW627 |
| **DESCRIPTION** | Particulate Filter-back |
| **NOTES** | |

## PARTS REQUIRED

| PART NO. | DESCRIPTION | QUANTITY | IN PACKAGE |
|---|---|---|---|
| **F5156** | **Adapter to OE Downpipe** | **1** | |
| CHC68SS | 68mm Band Clamp - 304 S/S | 1 | |
| **MSAU793REP** | **Centre Connecting Pipe** | **1** | |
| CHC83SS | 83mm Band Clamp - 304 S/S | 1 | |
| F20050 | 5.0mm Spacer | 2 | |
| **MSTIP252** | **Titanium 4.5" Trims** | **4** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 4 | |
| **MSVAG29** | **Rear Silencer Assembly** | **1** | |
| CHC83SS | 83mm Band Clamp - 304 S/S | 1 | |
| **MSVW511** | **Inner Outlet Pipes** | **2** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 2 | |
| **MSVW512** | **LH Valved Outlet Pipe** | **1** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 1 | |
| F3160 | Wire Formed Spring Assembly | 1 | |
| **MSVW513** | **RH Valved Outlet Pipe** | **1** | |
| CHC66.5SS | 66.5mm Band Clamp-304 S/Steel | 1 | |
| F3160 | Wire Formed Spring Assembly | 1 | |

MILLTEK

## TECHNICAL INFORMATION

| NOTES | OE rear silencer hanger brackets need to be rotated 180° as per below images: |
|---|---|

**OE Position:**



**Rotated 180°:**

