| | |
|---|---|
| **SYSTEM NO.** | SSXVW305 |
| **DESCRIPTION** | Cat-back |
| **NOTES** | |

## PARTS REQUIRED

| PART NO. | DESCRIPTION | QUANTITY | IN PACKAGE |
|---|---|---|---|
| **F5076** | **Adaptor Sleeve {60 I.D. to 70 O.D. X 110MM LONG}** | **1** | |
| CHC63SS | 63mm Band Clamp 304 S/Steel | 1 | |
| **MSSE134** | **Centre Silencer Replacement Pipe** | **1** | |
| CHC58SS | 58mm Band Clamp - 304 S/Steel | 1 | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| F5079 | Adaptor Sleeve 70mm 1.5 304 X 120mm (55.5 Id) | 1 | |
| **MSSE135** | **Rear Silencer Assembly** | **1** | |
| 8MMWASHER | 8mm Flat Washer Bzp | 1 | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |
| F7060 | Loose Xenon Sensor Bracket | 1 | |
| M8X16BZP | M8X16mm Bzp Set Screw-Zinc Pl. | 1 | |
| **MSVW407** | **Cerakote Black Tip Assembly** | **1** | |
| CHC73SS | 73mm Band Clamp 304 S/Steel | 1 | |

## TECHNICAL INFORMATION

F7060 Xenon sensor bracket location:

MILLTEK

