SYSTEM NO.	MCXAU109
DESCRIPTION	Downpipe-back
NOTES	Requires 4 holes to be drilled into the boot floor to allow fitment of the new exhaust hangers

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSAU638	**10V Adaptor Pipe**	**1**	
8MMWASHER	8mm Flat Washer Bzp	3	
F3010	Machined Olive M/Steel	1	
FLUR3	8mm Lasercut Flange	1	
M8BZPFLNUT	M8 Bzp Flange Nut Serrated Only	3	
M8X60BZP	M8 X 60mm Bzp Set Screw	3	
MSAU639	**Connecting Pipe**	**1**	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	1	
MSAU640	**Centre Silencer Assembly**	**1**	
893253147D	ECSM22 Vw/Audi Exhaust Rubber	1	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	1	
MSAU641	**Rear Silencer Assembly**	**1**	
8MMWASHER	8mm Flat Washer Bzp	4	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	1	
EBC4499	Mounting Rubber	2	
F20063	Marking Template	1	
F7066	Loose Mounting Cradle	2	
M8BZPFLNUT	M8 Bzp Flange Nut Serrated Only	4	
M8X16BZP	M8X16mm Bzp Set Screw-Zinc Pl.	4	
MSTIP193	**Titanium Tip Assembly**	**2**	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	2	

TECHNICAL INFORMATION

NOTES	Requires 4 holes to be drilled into the boot floor to allow fitment of the new exhaust hangers

MILLTEK

Master Copy Approved By: MILLTEK