SYSTEM NO.	SSXAU726
DESCRIPTION	Large Bore Downpipe and Hi-Flow Sports Cat
NOTES	Requires Stage 2 ECU Remap - Due to Design of Turbo Waste Gate fitting a decat can cause metallic rattle to be heard more than the OE Cat Downpipe

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSAU680	**High Flow 200cpsi Cat Assembly**	**1**	
10MMWASHER	10mm Flat Washer Bzp	2	
F3031	Gasket 1.5mm	1	
M10FLGNUT	M10 Bzp Flange Nutserrated Only	2	
M10X35BZP	M10 X 35mm Bzp Set Screw	2	
MSAU717	**Downpipe Turbo Elbow**	**1**	

TECHNICAL INFORMATION

NOTES	Requires Stage 2 ECU Remap - Due to Design of Turbo Waste Gate fitting a decat can cause metallic rattle to be heard more than the OE Cat Downpipe