SYSTEM NO.	**SSXAU817**
DESCRIPTION	Large-bore Downpipe and De-cat
NOTES	Requires Stage 2 ECU Remap - Due to Design of Turbo Waste Gate fitting a decat can cause metallic rattle to be heard more than the OE Cat Downpipe

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSAU717	**Downpipe Turbo Elbow**	**1**	
MSAU736REP	**Cat & OPF/GPF Bypass Assembly**	**1**	
10MMWASHER	10mm Flat Washer Bzp	2	
F3031	Gasket 1.5mm	1	
F3148	Aluminium Blanking Plug	4	
M10FLGNUT	M10 Bzp Flange Nutserrated Only	2	
M10X35BZP	M10 X 35mm Bzp Set Screw	2	

TECHNICAL INFORMATION

NOTES	Requires Stage 2 ECU Remap - Due to Design of Turbo Waste Gate fitting a decat can cause metallic rattle to be heard more than the OE Cat Downpipe