SYSTEM NO.	SSXAU598
DESCRIPTION	Full System
NOTES	Requires a stage 2 ECU remap (lambda cables need extending)

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSAU570REP	**Centre Silencer Replacement Assembly**	**1**	
8MMWASHER	8mm Flat Washer Bzp	1	
CHC73SS	73mm Band Clamp 304 S/Steel	2	
M8BZPFLNUT	M8 Bzp Flange Nut Serrated Only	1	
M8X16BZP	M8X16mm Bzp Set Screw-Zinc Pl.	1	
MSAU589	**ValveSonic LH Rear Silencer {OE motors to be re-used}**	**1**	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
F3160	Wire Formed Spring Assembly	1	
MSAU590	**ValveSonic RH Rear Silencer {OE Motors to be re-used}**	**1**	
CHC73SS	73mm Band Clamp 304 S/Steel	1	
F3160	Wire Formed Spring Assembly	1	
MSAU663	**LH 76mm Primary Cat Bypass Downpipe (fits LH Turbo) {Cerakote Semi-Gloss Black Finish}**	**1**	
MSAU664	**RH 76mm Primary Cat Bypass Downpipe (fits RH Turbo) {Cerakote Semi-Gloss Black Finish}**	**1**	
MSAU665REP	**LH Connecting Pipe to Milltek Catback**	**1**	
10MMWASHER	10mm Flat Washer Bzp	3	
F3114	Gasket 1.5mm	1	
M10FLGNUT	M10 Bzp Flange Nutserrated Only	3	
M10X35BZP	M10 X 35mm Bzp Set Screw	3	
MSAU666REP	**RH Connecting Pipe to Milltek Catback**	**1**	
10MMWASHER	10mm Flat Washer Bzp	3	
F3114	Gasket 1.5mm	1	
M10FLGNUT	M10 Bzp Flange Nutserrated Only	3	
M10X35BZP	M10 X 35mm Bzp Set Screw	3	

MILLTEK

TECHNICAL INFORMATION

NOTES	Requires a stage 2 ECU remap (lambda cables need extending)