SYSTEM NO.	SSXHY121
DESCRIPTION	Cat-back
NOTES	

PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
MSHY101	**Connecting Pipe**	**1**	
CHC79SS	79mm Band Clamp - 304 S/S	1	
MSHY102	**Axle Pipe**	**1**	
CHC79SS	79mm Band Clamp - 304 S/S	1	
MSHY103	**Rear Silencer**	**1**	
CHC79SS	79mm Band Clamp - 304 S/S	1	
MSHY104	**LH Outlet Pipe**	**1**	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	1	
MSHY105	**RH Outlet Pipe with Valve {Re-uses the OE Valve Motor}**	**1**	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	1	
MSHY107	**GPF Delete Pipe**	**1**	
MSTIP252	**4.5" Brushed Titanium Tips**	**2**	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	2	

TECHNICAL INFORMATION

NOTES	